



Important!

Please give copies to all
your VW Technicians

Technical Bulletin

Subject: Exterior Lights, Moisture Accumulation

Group: 94

Number: 06-02

Model(s): All

1996 ► 2007

Date: Feb. 27, 2006

Supersedes T.B. Group 94 number 03-01 dated August 1, 2003 due to additional models and model years.

Condition

Condensation and/or water droplets visible on inside of exterior light lenses.

Service

- ◆ Exterior light assemblies (headlights, taillights, fog lights, turn signals) are vented and may collect moisture on their inner surfaces, depending on humidity and other climatic changes.
- ◆ For headlights, the affected lens surface should be clear after approx. 10 minutes of light operation, although the entire surface may not clear.



Tip:

Condensation does not affect performance of light assemblies.

In cases where larger water droplets have formed on the inside of the lens or significant amount of water has collected at the bottom of a light assembly:

- Check for leaking seals, cracks in lenses or assemblies.

DO NOT replace light or lens assemblies for this condition (unless damage is found).

If damage to seals or cracks to lenses or assemblies are found:

- ◆ Follow normal repair procedures for this type of failure (provide a photograph, if possible, with repair documentation for verification).

If no damage is found, use compressed air (less than 30 PSI) to blow out the lens.