

Technical Bulletin



Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat, Passat Wagon	2006 - 2007	2.0L (BPY)	All	All	All
GTI	2006 - 2007	2.0L (BPY)	All	All	All
Jetta (A5)	2005 - 2007	2.0L (BPY)	All	All	All
Eos	2006 - 2007	2.0L (BPY)	All	All	All

Condition

15 07 05 Nov. 14, 2007 2015153, Supersedes Technical Bulletin Group 15 number 07-04 dated June 29, 2007 due to fuel pump replacement clarification.

MIL ON, DTC P0087, P1093 or P2293 Stored in ECM Fault Memory

MIL ON with the following DTCs may be stored in ECM fault memory:

DTC	Description
P0087	Fuel Rail / System Pressure - Too Low
P1093	Fuel Trim 2, Bank 1 Malfunction
P2293	Fuel Pressure Regulator 2 Performance

Technical Background

Excessive wear of intake camshaft lobe that drives the high pressure fuel pump. The wear limits maximum pump piston lift, causing fuel rail pressure fluctuations.

The wear on the camshaft lobe can also lead to wear on the base of the high pressure fuel pump cam follower.



Note:

Please review with customer the importance of using proper engine oil. Use of engine oil that does not meet VW quality standards can cause premature wear to engine components. Refer to Technical Bulletin 17-07-14 *Engine Oils Which Meet Volkswagen Oil Quality Standards VW 502 00, VW 505 01 and VW 504 00/507 00.*

Production Solution

Increase surface hardening of camshaft lobe for the high pressure fuel pump. Improved intake camshafts have Part No. 06F109101B.

Technical Bulletin




Service

If there are low pressure faults stored in the ECM like P310b or P129f, always diagnose low pressure faults first before diagnosing high pressure faults.



Note:

DO NOT REPLACE high pressure pump for low pressure faults.



Remove the high pressure fuel pump and visually inspect:

1. Base surface of the cam follower -6- in contact with the camshaft lobe.
2. Tip of the high pressure fuel pump plunger.
3. High pressure fuel pump camshaft lobe.



If the base of the cam shaft follower looks like -C- or -D-, no excessive wear is present.

Cam follower and camshaft should NOT be replaced.

If the cam follower base surface is excessively worn so that its surface is concave -B- or missing -A-, inspect the intake cam shaft lobe for wear.



If the high pressure fuel pump camshaft lobe shows excessive wear, replace the intake camshaft with Part No. 06F109101B and the cam follower with Part No. 06D109309C, see Group 15 Engine - Cylinder head, Valvetrain in ElsaWeb.

Technical Bulletin



Inspect the tip of the high pressure fuel pump plunger for excessive wear.



Note:

If plunger tip of fuel pump is **NOT WORN**, **DO NOT REPLACE** the fuel pump.

If excessive wear is found the high pressure pump must also be replaced, see Group 20 Fuel Supply in ElsaWeb.



Tip:

High pressure fuel pump plunger damage is only possible if the cam follower base has a hole in it and the plunger tip has come in direct contact with the camshaft lobe.


If no excessive wear can be found in the high pressure fuel pump cam follower or intake camshaft lobe, or if the damage is found in camshafts with part number 06F109101B, create a Technical Assistance Contact Ticket under the Concern Type Engine and Engine Electronics in ElsaWeb.

Attach the complete diagnostic log to the contact, and call the VW Technical Assistance Center for further assistance.

Warranty

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual*

Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Eos	2006 - 2007	2.0L (BPY)	All	All	All
GTI	2006 - 2007	2.0L (BPY)	All	All	All
Jetta (A5)	2005 - 2007	2.0L (BPY)	All	All	All
Passat, Passat Wagon	2006 - 2007	2.0L (BPY)	All	All	All



Technical Bulletin



Claim Type:	Use applicable Claim Type*		
SAGA Coding			
Service Number:	Damage Code	Damage Location (Depends on Service No.)	Parts Manufacturer (removed part)
1505	0018	Use applicable when indicated in ElsaWeb (L/R)	___**
WIN Coding			
Part Identifier:	1505		
Damage Code:	1505 18 ___** 2		
Labor Operation: 2.0T FSI Engine	1505 19XX = use applicable labor operations for specific model & 2.0L turbo FSI engine in ElsaWeb		
Diagnostic Time***			
GFF Time expenditure	WIN) 01509999 = XX TU (actual print out time)		YES
	SAGA) 01500000 = XX TU (actual print out time)		
Road Test	01210002 & 01210004		NO
Technical Diagnosis	01320026 = 100 TU max.		YES
Claim Comment: Input "As per Technical Bulletin 2015153" in comment section of Warranty Claim.			

* Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only.

** Code per warranty vendor code policy.

*** Documentation required per Warranty Policy & Procedures Manual.

Required Parts and Tools

Description	Part No:	Quantity
Intake Cam Shaft	06F109101B	1
Cam Follower	06D109309C	1

No Special Tools required.

Technical Bulletin



Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

