

Technical Bulletin



Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat	2006	3.6L (BLV)	All	All	All
Passat	2007	3.6L (BLV)	All	3C_7E000001 3C_7P000001	3C_7E049813 3C_7P079584
Passat Wagon	2007	3.6L (BLV)	All	3C_7E000001	3C_7E105742
Touareg	2007	3.6L (BHK)	All	7L_7D000001	7L_7D026595

Condition

01 08 03 Jan. 22, 2008 2017105

MIL and EPC light ON, DTC P0016 Stored in ECM Fault Memory

Customer may report:

- EPC light ON and slightly reduced engine torque because vehicle is in E-Gas Safety Mode.

Only in combination with:

- MIL ON and the following DTC stored in ECM fault memory:

DTC	Description
P0016	Crankshaft Position - Camshaft Position - Correlation Bank 1 Sensor A

Customer may also report:

- Excessive clacking or rattling noise from engine area – more audible at idle.

Technical Background

Condition may be caused by the correlation between crankshaft and camshafts out of tolerance.

Production Solution

No production change required.

Technical Bulletin



Service



Note:

For the condition described in this bulletin, contact technical assistance by selecting the "Technical Assistance" tab in ElsaWeb and follow the instructions to obtain a 6 digit access code.

Warranty

Information only.

Required Parts and Tools



Tip:

The Volkswagen Technical Helpline instructions determine which parts are required for the repair.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.