

Technical Bulletin



Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat, Passat Wagon	2007	All	All	3C_7E143905 3C_7P068990	3C_7E999999 3C_7P999999
Rabbit, GTI	2007	All	All	1K_7W061194	1K_7W999999
Touareg	2007	All	All	7L_7D057930	7L_7D999999

Condition

92 08 01 Apr. 10, 2008 2017605

Rain Sensor Damaged during Removal

Damage to rain sensor during windshield replacement.



Note:

The condition as described DOES NOT compromise manual windshield wiper operation.

Technical Background

Adhering gel pad used to attach sensor to windshield is strong, making sensor difficult to remove without damage.

Production Solution

Production changed with MY 2008.

Service



Tip:

If a replacement windshield is installed due to manufacturer defect, outside influence (stone chip) or collision repair, and the sensor IS NOT the cause of complaint, the rain sensor can be claimed as warranty repair.



Note:

Replacement of the rain sensor during windshield replacement is a ONE TIME customer courtesy.

Technical Bulletin



Example:

The windshield has to be replaced due to stone chip damage. During windshield replacement process the original rain sensor needs to be adapted to new windshield. Removing the rain sensor from the original windshield causes the sensor to become inoperative or physically damaged.



Note:

In addition to claim comment per warranty table, enter production date of sensor in SAGA 2 comments box.

Example:

Date on rain sensor 03-04-2007 (white arrow).

Warranty

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾					
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Passat, Passat Wagon	2007	All	All	3C_7E143905 3C_7P068990	3C_7E999999 3C_7P999999
Rabbit, GTI	2007	All	All	1K_7W061194	1K_7W999999
Touareg	2007	All	All	7L_7D057930	7L_7D999999
Claim Type:	Use applicable Claim Type ¹⁾				
SAGA Coding					



Technical Bulletin



Service Number:	Damage Code	Damage Location (Depends on Service No.)	Parts Manufacturer (removed part)
9212	0010	Use applicable when indicated in ElsaWeb (L/R)	--- ²⁾
Labor Operation ³⁾ :		92121900 = 30 TU	
Diagnostic Time ⁴⁾			
GFF Time expenditure	01500000 = XX TU max.		NO
Road Test	01210002 & 01210004		NO
Technical Diagnosis	0132xxxx = XX TU max.		NO
Claim Comment: Input "As per Technical Bulletin 2017605" in comment section of Warranty Claim.			
¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only ²⁾ Code per warranty vendor code policy. ³⁾ Labor Time Units (TUs) are subject to change with Elsa updates. ⁴⁾ Documentation required per Warranty Policy & Procedures Manual.			

Required Parts and Tools

No Special parts Required.

No Special Tools Required.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.