

# Technical Bulletin



---

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	2005 - 2009	All	All	All	All

## Condition

80 08 01 Jul. 31, 2008 2018424

### Reduced Heating Performance

Customer may perceive heater output inadequate.

 **Note:**

The condition as described does not compromise visibility.

## Technical Background

The addition of aftermarket cooling system sealers may affect the hydrodynamics of the cooling system, therefore reducing coolant flow and the ability to exchange heat properly.

## Production Solution

No production change required.

## Service

 **Note:**

**DO NOT** use cooling system sealants of any kind.

Volkswagen Group of America does not recommend use of cooling system sealants.

Cooling system flush, drain and refill, or partial drain and refill IS NOT a warrantable item.

# Technical Bulletin

---



## Warranty

Information Only.

## Required Parts and Tools

No Special Parts Required.

## Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.