

Technical Bulletin



Condition

PDI - Tire Pressure Monitoring, DTC 00677 008 Stored When Vehicle is in Transport Mode

Tire Pressure Monitoring Diagnostic Trouble Code (DTC) 00667 008 is found at the PDI.

- No communication with ambient air temperature sensor when vehicle is in Transport Mode.
- When Transport Mode is switched OFF, DTC becomes sporadic and additional DTC 02802, with no additional text, may be displayed.

44 06 05 Aug. 8, 2006 2010520 Supersedes T.B. Group 44 number 05-02 dated August 15, 2005 due to updated information.

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
New Passat	2006-2007	All	All	All	All
New Passat Wagon	2006-2007	All	All	All	All

Technical Background

Software related.



Tip:

[Transport Mode Must always be switched OFF before beginning diagnosis of any vehicle system.](#)

Production Solution

No production change required.



Technical Bulletin



Service

With VAS 5051 / VAS 5052 Diagnostic tool connected and Transport Mode is Switched OFF:

- Erase DTC.
- Recheck DTC memory.

If DTC returns:

- Continue to diagnose condition.

If DTC does not return:

- No additional work necessary.

Warranty



Tip:

[Procedure is included in the P. D. I., No additional time is allowed.](#)

Required Parts and Tools

No Special Tools required.

No Special Parts required. Always see ETKA for the latest part(s) information.