

# Technical Bulletin



## Condition

Electrically Folding Side View Mirror, Whistling Noise

66 06 04 Oct. 20, 2006 2013172

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat, Passat Wagon	2007	All	All	All	All

## Technical Background

A wiring harness may interfere with the proper installation of the mirror cover to the mirror housing, possibly leaving a small gap.

## Production Solution

Installation of adhesive backed bumper Part No: ZVW269008 to the electrically folding mirror to improve wire harness route and prevent mirror half separation appearance as of CW 30/06.

## Service



A wiring harness may interfere with the proper installation of the mirror cover to the mirror housing, possibly leaving a small gap.

While driving, air can enter the gap causing a whistling noise.

Applying an adhesive backed bumper Part No: ZVW269008 will prevent the wire harness from interfering with the proper installation of the mirror housing cover.

# Technical Bulletin



- Separate mirror housing, see ElsaWeb - Repair Manual, BODY, Body Exterior, 66 Exterior equipment, Exterior rear view mirror for housing disassembly.

- Insert adhesive backed bumper Part No: ZVW269008 on the inner aluminum casting.



Tip:

This retains the wiring harness away from the white plastic clip.

- Assemble mirror housing, see ElsaWeb - Repair Manual, BODY, Body Exterior, 66 Exterior equipment, Exterior rear view mirror for housing disassembly.



Tip:

Part number(s) are for reference only. Always see ETKA for the latest part(s) information.

## Warranty

When procedure applies to vehicles within the New Vehicle Limited Warranty, use the following:	
Claim Type:	W2
Part Identifier:	6679
Damage Code:	6679 11 000 1
Labor Operation:	66791999 = 40 TU
Diagnostic Time:	No Additional Diagnostic Time Allowed
Claim Comment: Input "As per Technical Bulletin 2013172" in comment section of Warranty Claim.	

\* Code per warranty vendor code policy.

## Required Parts and Tools

Description	Part No:	Quantity
Adhesive Backed Bumper	ZVW269008	2

No Special Tools required.