

# Technical Bulletin



## Condition

PDI - Increased Current Draw While Vehicle is in Transport Mode

27 06 07 Nov. 20, 2006 2013384

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat, Passat Wagon	2007	All	All	3C_7E000001	3C_7E116433
Passat	2007	All	All	3C_7P000001	3C_7P084250

## Technical Background

The interaction between TPMS and Comfort Control modules caused increased current draw for a group of vehicles. Affected vehicles were shipped from the factory out of transport mode.

## Production Solution

As of CW 45/06 the software issue has been resolved and vehicles are shipped in transport mode again.

## Service

Vehicles received within the VIN range should not be stored in transport mode at port or dealer locations.

## Warranty

Information only.



Tip:

[Procedure is included in the PDI. Do Not claim additional labor for this operation.](#)

## Required Parts and Tools

No Special Tools required.

No Special Parts required. Always see ETKA for the latest part(s) information.