

# Technical Bulletin



Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Rabbit/GTI (A5)	2006, 2007	All	All	All	All
Passat Sedan (B6)	2006, 2007	All	All	All	All

## Condition

94 07 03 August 13, 2007 2015936

License Plate Lights, Water Intrusion

License Plate light seal corrodes allowing water/moisture to enter lamp socket.

## Technical Background

Not applicable.

## Production Solution

New lens plate seal for MY 2008

## Service

- Install new lens, torque = 1 Nm +/- 0.5

# Technical Bulletin



## Warranty

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual	
Claim Type:	Use applicable Claim Type**
Part Identifier:	9429
Damage Code:	9429 33 ___ * 2
Labor Operation:	
Passat	9429 2099 = 30 TU
Rabbit/GTI	9429 2099 = 20 TU
Diagnostic Time:	No diagnostic time allowed
Claim Comment: Input "As per Technical Bulletin 2015936" in comment section of Warranty Claim.	

\* Code per warranty vendor code policy.

\*\* Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only.

## Required Parts and Tools

Part Description	Part No:	Quantity
License Plate Light (Passat)	3C5 943 021	1 (pair)
License Plate Light (Rabbit/GTI)	3D0 943 021A	1 (pair)

No Special Tools required.

## Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.