

Technical Bulletin



Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat, Passat Wagon	2006 - 2008	All	All	All	All

Condition

80 07 08 Nov. 28, 2007 2016869

Heater, Output Perceived as Insufficient, Climatronic System Only



Note:

The condition as described does not compromise visibility.


Technical Background

Customer may comment that the air coming out of the driver or passenger side vent is not warm enough.

Production Solution

No production change required.

Service



Diagnose the -G150- and/or -G151- temperature sensor (arrows) using normal GFF protocol.



Tip:

-G150- sensor is located behind driver's side instrument panel cover, in the vent tube (next to the fuse panel), -G151- sensor is located on passenger side in the vent tube.



Technical Bulletin



Warranty

Information only.

Required Parts and Tools

No Special Parts required.

Tool Description	Tool No:
VAS Diagnostic Tool	VAS 5051/5052

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.