

# Technical Bulletin



Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
(A5) Jetta	2005 - 2008	All	All	All	All
Rabbit, GTI, R32, Passat, Passat Wagon	2006 - 2008	All	All	All	All

## Condition

91 08 07 May 22, 2008 2017830

Radio Label, Delphi Part Numbers

Incorrect interpretation of radio part number on radio label.

## Technical Background

Radios are being ordered incorrectly, because radio part labels are being misread

## Production Solution

No Production Change Required.

## Service

Identify radio label part numbers using the following examples:



Part Label is Part No. 1K0 035 180

# Technical Bulletin



Part Label is Part No. 1K0 035 180 C



Part Label is Part No. 1K0 035 180 D



# Technical Bulletin



Part Label is Part No. 1K0 035 180 L



Tip:

Pay careful attention and use radio Part No. (P/N), when ordering radio.

Other part numbers are similar.

Radio Part No. may also be obtained by the use of a scan too, view address word 56 Radio.

## Warranty

Information only.

## Required Parts and Tools

No special parts required.

No special tools required.

## Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.